Andy Tiernan Classics

The Old Railway Station Framlingham Suffolk IP13 9EE Tel 01728 724321

Used Antique Motorcycle	Brief I	Evalua	Dated 18/06/2021		Tester AMC					
Make BSA	Model A10			Year 1955	Reg No 67		678 XVH	Oils checked E, G, P		
Price £5 ,500	Colour Red				Stock No 07695BSA			cc 650		
VIN/Frame CA7.13127			Location Hea	adstock		Engine No CA10.7185				
Registration Documents: Latest DVLA V5C registration document MOT expiry Exempt										
History . Last owned by a lady form Leicestershire										

		Nice	Mean	Poor	COMMENTS			
	Headlamp Operation	✓						
	Rear lamp Operation	✓						
	Stop lamp Operation	✓						
TRIC	Horn Operation	√						
જે	Charging System Operation	√						
	Battery	✓			Voltage = 6	Earth polarity = Neg. Fuse fitted		
EERI	Head Bearings	√						
	Forks	√						
	Swing Arm Bearings	√						
	Wheel Alignment	√						
	Girder Links If Applicable	n/a						
	Front Brake	√						
	Rear Brake	√						
S	Controls Clevis Pins etc	√						
	Front Tyre tread depth	√			Size 3.25 x 19	(See note 3 below) Dunlop		
	Rear Tyre tread depth		√		Size 4.10 x 19	(See note 3 below) Avon (aged)		
	Front Bearings	√						
	Rear Bearings		√					
	Front Rim	✓			Plating = 80%			
	Rear Rim	✓			Plating = 90%			
	Front Spokes	✓				·		
	Rear Spokes	✓						
GENI	Exhaust Silencers	✓			Plating = 95%			
	Exhaust Pipes	√			Plating = 95%			
	Fuel System Leaks	✓				·		
	Speedo	✓			Reading = 22887			
	Cables	✓				·		
	Handle bars/Levers	✓			Plating = 85%			
	Final Drive Chain		✓			·		
	Primary Chain Tension	✓						
	Engine Condition	✓						
	Cold Starting	✓						
	Hot Starting	✓						
			lrops un	der the	engine after the roa	d test		
	Gearbox operation	✓			No of gears 4			
	Clutch operation	✓				·		
	Road Test Evaluation	✓			Distance covered 10 miles			
	Carburettor				Type = Amal Monobloc			

Tester reports – The engine started readily from cold & when hot & ran well, pulling strongly from low revs, happily sitting at 55 to 60 mph. The clutch worked without fault. All the gears selected & functioned normally. Both the period brakes worked as well as you would expect. This was a pleasing machine to ride.

Notes: -

- 1. This report is only the opinion of the tester on the day and should only be considered as a rough guide as time does not permit an in depth report. Antique machines will always require ongoing work.
- All antique machines must be thoroughly checked over & fully serviced by a competent mechanic before any use, due to their age & the length of time that they may have been stored.
- WWW.ROSPA.com recommends tyres that have been in storage for over 6 years or in use for 10 years should be replaced. For further information on tyre safety visit the
 ROSPA website page at <a href="http://www.rospa.com/roadsafety/adviceandinformation/vehiclesafety/tyresafet
- 4. The speedometer (if fitted) reading shown in this report is not necessarily an indication of the machines true mileage.
- 5. We strongly recommend that all Flat tank motorcycles are run on **Ethanol Free** petrol, such as Aspen or Avgas.