## **Andy Tiernan Classics**

## The Old Railway Station Framlingham Suffolk IP13 9EE Tel 01728 724321

Used Antique Motorcycle	e Brief Evalu	Dated 01/08/2019		Tester AMC				
Make BSA	Model S28		<b>Year</b> 1928		Reg No DS 9429		Oils checked E, G	
<b>Price £</b> 9,850	Col	our Green & b	lack	Stock No 07	7223BSA		<b>cc</b> 500cc	
VIN/Frame GS12475		Location LH	S under saddle		Engine No M.21506.			
Registration Documents: Current DVLA V5C registration document MOT expiry Exempt								
History. First registered on the 1st of September 1928								

		Nice	Mean	Poor	COMMENTS			
io.	Headlamp Operation	See	note	$\rightarrow$	Acetylene lights fitted, not tested			
	Rear lamp Operation	366	note	$\uparrow$	Acetylene lights litted, not tested			
	Stop lamp Operation	n/a						
	Horn Operation	n/a						
	Charging System Operation	n/a						
	Battery	n/a						
STEERING SUSPENSION	Head Bearings	$\checkmark$						
	Forks	$\checkmark$						
	Swing Arm Bearings	n/a						
	Wheel Alignment							
	Girder Links If Applicable		$\checkmark$					
BRAKES	Front Brake							
	Rear Brake		$\checkmark$		Judders slightly			
	Controls Clevis Pins etc	$\checkmark$						
	Front Tyre tread depth	$\checkmark$			Size 3.00 x 20 (see note 3 below) Avon			
	Rear Tyre tread depth	$\checkmark$			Size 3.00 x 20 (see note 3 below) Dunlop (aged)			
	Front Bearings	$\checkmark$						
	Rear Bearings	$\checkmark$						
	Front Rim	$\checkmark$			Plating = $n/a$ Painted			
	Rear Rim	$\checkmark$			Plating = $n/a$ Painted			
	Front Spokes	$\checkmark$						
	Rear Spokes	$\checkmark$						
GENERAL	Exhaust Silencers		$\checkmark$		Plating = 80%			
	Exhaust Pipes	$\checkmark$			Plating = 85%			
	Fuel System Leaks	$\checkmark$						
	Speedo	n/a						
	Cables	$\checkmark$						
	Handle bars/Levers	$\checkmark$			Plating = 95%			
	Final Drive Chain		$\checkmark$					
	Primary Chain Tension	$\checkmark$						
	Engine Condition	$\checkmark$						
	Cold Starting	$\checkmark$						
	Hot Starting	$\checkmark$						
	Oil Leaks	A few d	lrops un	der the	engine after the road test			
	Gearbox operation	$\checkmark$			No of gears 3			
	Clutch operation	$\checkmark$						
	Road Test Evaluation	$\checkmark$			Distance covered 12 miles			
	Carburettor	$\checkmark$			Type = Amal side float			
Tastas	aster reports. The engine started readily both from cold & bot & rep well. Acceleration was brick & the bile hennily set							

Tester reports – The engine started readily both from cold & hot & ran well. Acceleration was brisk & the bike happily sat at 40 to 45 mph. The clutch action was light & functioned without fault. All the gears selected cleanly & worked normally. Both period brakes worked for their size. The bike handled nicely & was pleasing to ride.

Notes: -

<sup>1.</sup> This report is only the opinion of the tester on the day and should only be considered as a rough guide as time does not permit an in depth report. Antique machines will always require ongoing work.

<sup>2.</sup> All antique machines must be thoroughly checked over & fully serviced by a competent mechanic before any use, due to their age & the length of time that they may have been stored.

WWW.ROSPA.com recommends tyres that have been in storage for over 6 years or in use for 10 years should be replaced. For further information on tyre safety visit the ROSPA website page at <u>http://www.rospa.com/roadsafety/adviceandinformation/vehiclesafety/tyresa</u>

<sup>4.</sup> The speedometer (if fitted) reading shown in this report is not necessarily an indication of the machines true mileage.

<sup>5.</sup> We strongly recommend that all Flat tank motorcycles are run on **Ethanol Free** petrol, such as Aspen or Avgas.