Andy Tiernan Classics

The Old Railway Station Framlingham Suffolk IP13 9EE Tel 01728 724321

Used Antique Motorcycle	Brief H	Evalua	Dated 28/10/2021		Tester AMC				
Make Sunbeam	Model	S7	Year 1954		Reg No RFO 174		Oils checked E, G, P		
Price £ 7,650		Col	our Green & black	Stock No 07959SBM		[cc 500		
VIN/Frame S7-7008			Location LHS under saddle	Engine No S8-11959					
Registration Documents: Latest DVLA V5C registration document MOT expiry Exempt									
History. Originally registered on the 6th of March 1954									

		Nice	Mean	Poor	COMMENTS		
	Headlamp Operation	\checkmark					
ELECTRICS	Rear lamp Operation	\checkmark					
	Stop lamp Operation	\checkmark					
	Horn Operation	\checkmark					
	Charging System Operation	\checkmark					
	Battery	\checkmark			Voltage = 6 Earth polarity = Pos. Fuse fitted		
STEERING SUSPENSION	Head Bearings	\checkmark					
	Forks	\checkmark					
	Swing Arm Bearings	n/a					
	Wheel Alignment	\checkmark					
	Girder Links If Applicable	n/a					
BRAKES	Front Brake		\checkmark				
	Rear Brake	\checkmark					
	Controls Clevis Pins etc	\checkmark					
	Front Tyre tread depth	\checkmark			Size 5.00 x 16 (See note 3 below) Avon		
	Rear Tyre tread depth	\checkmark			Size 5.00 x 16 (See note 3 below) Avon		
WHEELS TYRES	Front Bearings		\checkmark				
	Rear Bearings	\checkmark					
	Front Rim	\checkmark			Plating = n/a Painted		
	Rear Rim	\checkmark			Plating = n/a Painted		
	Front Spokes	\checkmark					
	Rear Spokes	\checkmark					
GENERAL	Exhaust Silencers	\checkmark			Plating = n/a Stainless steel		
	Exhaust Pipes	\checkmark			Plating = n/a Stainless steel		
	Fuel System Leaks	\checkmark					
	Speedo	\checkmark			Reading = 48144		
	Cables	\checkmark					
	Handle bars/Levers	\checkmark			Plating = 90%		
	Final Drive Chain	n/a					
	Primary Chain Tension	n/a					
	Engine Condition		\checkmark		Blowing head gasket		
	Cold Starting	\checkmark					
	Hot Starting	\checkmark					
	Oil Leaks		g to note				
	Gearbox operation	\checkmark			No of gears 4		
	Clutch operation	\checkmark					
	Road Test Evaluation	\checkmark			Distance covered 7 miles		
	Carburettor \checkmark Type = Amal side float						
Factor	star reports. The engine started readily from cold & bot & rep well, hennily sitting at 50 to 55 mph. The clutch worked without fault						

Tester reports – The engine started readily from cold & hot & ran well, happily sitting at 50 to 55 mph. The clutch worked without fault. All the gears selected & functioned normally. Both the period brakes worked with the rear being better than the front which would benefit from attention. A smooth & comfortable motorcycle!

Notes: -

^{1.} This report is only the opinion of the tester on the day and should only be considered as a rough guide as time does not permit an in depth report. Antique machines will always require ongoing work.

^{2.} All antique machines must be thoroughly checked over & fully serviced by a competent mechanic before any use, due to their age & the length of time that they may have been stored.

WWW.ROSPA.com recommends tyres that have been in storage for over 6 years or in use for 10 years should be replaced. For further information on tyre safety visit the ROSPA website page at http://www.rospa.com/roadsafety/adviceandinformation/vehiclesafety/tyresafety/

^{4.} The speedometer (if fitted) reading shown in this report is not necessarily an indication of the machines true mileage.

^{5.} We strongly recommend that all Flat tank motorcycles are run on **Ethanol Free** petrol, such as Aspen or Avgas.