Andy Tiernan Classics

The Old Railway Station Framlingham Suffolk IP13 9EE Tel 01728 724321

Used Antique Motorcyc	le Brief E	Evalua	Dated 19/02/2024		Tester AMC			
Make Panther	Model 100			Year 1954		Reg No PFJ 484		Oils checked E, G, P
Price £ 6,650	Colour Re		our Red, white	Red, white & black		Stock No 08740pth		cc 600
VIN/Frame 23525			Location Under saddle nose			Engine No 54M663E		
Registration Documents: DVLA V5C registration document MOT expiry Exempt								
History. First registered in Exeter on the 11th of August 1954								

		Nice	Mean	Poor		COMMENTS		
E L	Headlamp Operation	\checkmark						
3	Rear lamp Operation	\checkmark						
r R	Stop lamp Operation	n/a						
2	Horn Operation	\checkmark			Bulb type fitted			
5	Charging System Operation	\checkmark						
SS TU ES EP RE IN	Battery	\checkmark			Voltage = 6	Earth polarity = Neg. Fuse fitted		
	Head Bearings	\checkmark						
	Forks	\checkmark						
	Swing Arm Bearings	n/a						
N S G I	Wheel Alignment		\checkmark					
O N B R A K E S	Girder Links If Applicable	n/a						
	Front Brake	\checkmark						
	Rear Brake		\checkmark					
	Controls Clevis Pins etc	\checkmark						
E R E E L S	Front Tyre tread depth	\checkmark			Size 3.50 x 19	(See note 3 below) Avon		
	Rear Tyre tread depth	\checkmark			Size 3.50 x 19	(See note 3 below) Dunlop		
	Front Bearings	\checkmark				· · · · · · · · · · · · · · · · · · ·		
	Rear Bearings	\checkmark						
	Front Rim	\checkmark			Plating = 80%			
	Rear Rim	\checkmark			Plating = 85%			
	Front Spokes	\checkmark						
	Rear Spokes	\checkmark						
G E R A L	Exhaust Silencers	\checkmark			Plating = 90%			
	Exhaust Pipes		\checkmark		Plating = n/a	Painted		
	Fuel System Leaks	\checkmark						
	Speedo	\checkmark			Reading = 09410			
	Cables		\checkmark					
	Handle bars/Levers	\checkmark			Plating = 90%			
	Final Drive Chain		\checkmark					
	Primary Chain Tension	\checkmark						
	Engine Condition	\checkmark						
	Cold Starting	\checkmark						
	Hot Starting	\checkmark						
	Oil Leaks	Nothing	g to note					
	Gearbox operation	\checkmark			No of gears 4			
	Clutch operation	\checkmark						
	Road Test Evaluation	\checkmark			Distance covered 8 miles			
	Carburettor	\checkmark			Type = Amal 289 side float			

Tester reports – Started readily from cold & when hot. The motor ran well & pulled like a train from low revs. The clutch worked without fault. All gears selected & functioned normally. Both period brakes worked with the front being better than the rear, which would benefit from some attention. The bike rode well & was a very congenial machine on test!

Notes: -

^{1.} This report is only the opinion of the tester on the day and should only be considered as a rough guide as time does not permit an in depth report. Antique machines will always require ongoing work.

^{2.} All antique machines must be thoroughly checked over & fully serviced by a competent mechanic before any use, due to their age & the length of time that they may have been stored.

WWW.ROSPA.com recommends tyres that have been in storage for over 6 years or in use for 10 years should be replaced. For further information on tyre safety visit the ROSPA website page at <a href="http://www.rospa.com/roadsafety/adviceandinformation/vehiclesafety/tyresafet

^{4.} The speedometer (if fitted) reading shown in this report is not necessarily an indication of the machines true mileage.

^{5.} We strongly recommend that all Flat tank motorcycles are run on **Ethanol Free** petrol, such as Aspen or Avgas.